## SHIELDme<sup>TM</sup> TOUCHLESS TEMPERATURE MEASUREMENT





## **TECHNICAL DATA**

Accuracy	±0.2 degrees	Response Time	0.5s
Abnormal automatic alarm	flashing + "Di Di" sound	Charging Method	USB charging or battery
Automatic measurement	measuring distance 5cm ~ 10cm)	Input	USB DC 4.2-5V
Standby	About one week	Weight	350g
Install method	nail hook, double-sided adhesive sticking, bracket fixing	Dimensions	170*115*140mm
Operating temperature	10°C ~ 40°C (Recommend 15°C ~ 35°C)	Infrared measuring range	0 ~ 50°C
Standby	5s (Red dot dynamic cycle)	Screen	Digital display







High Accuracy



Alarm Function



One Week Standby



°C°F Unit Available



°C°F Unit Available

<sup>\*</sup>We reserve the right to change specifications of our product without prior notice.